

2U Global OCA DC Power Supply Adapter Kit User Guide

REQUIRED MATERIALS

DC Power Supply Conversion Kit Containing:

- Supermicro Power Supply Unit, PWS-1K11P-1R x 2
- DC Hookup Cable, MBX-255816-R01 x 2




WARNING!

Ensure the system is powered down and unplugged before proceeding

REWORK INSTRUCTIONS

DC PSU Terminal Prep

1. With a flathead screwdriver loosen the -48V and RTN terminals.



2. With a Phillips-head screwdriver loosen the ground terminal.



2U Global OCA DC Power Supply Adapter Kit User Guide

DC PSU Wiring

1. Black Wire = -48V | Red Wire = RTN | Green Wire = Ground
Remove the wire installation from the tips of the wires.



2. Insert the wires into the following terminals.
Black Wire = -48V | Red Wire = RTN | Green Wire = Ground
Tighten the terminals with the appropriate screwdrivers.
Pull back on the wires to ensure they are secured.

